



Flight Light Inc.
 2708 47th Ave.
 Sacramento, California, U.S.A.
 95822-3806



**Precision Approach Path
 Indicator Lighting (PAPI)
 FAA L-880 & L-881**

PH (916) 394-2800 FX (916) 394-2809
 TF (800) 806-3548 EM info@flightlight.com

Compliance

Certified FAA L-880 & L-881
 AC 150/5345-28 (Current Edition)

Features

- Provides the correct glide slope from over 10 miles away.
- Reliable photometric performance.
- Stable housing results in fewer shut-downs for realignment, reducing maintenance and increasing airfield utilization.
- LED indicator identifies tilt switch circuit fault.
- Quartz halogen average rated lamp life is 1000 hours.
- No optical bench or special tools required for servicing.
- Intuitive design of aiming device simplifies setting elevation and azimuth angles.
- Interlock feature allows PAPI operation only in conjunction with runway lights (optional).



Ordering Code

| FAA Type | FAA Style | Class | Options |
|--------------------|-----------------|--------------------------|------------------------------------|
| 880: 4 light units | V: Voltage | 2: Down to -67°F (-55°C) | 1: Runway Interlock (voltage only) |
| 881: 2 light units | C: Current 6.6A | | 4: 4-leg light units* |

* Standard system has 3 legs per light unit.

Visit our web site: www.flightlight.com